Service Fees

REGULATOR EVALUATION \$39

12 POINT INSPECTION

REGULATOR SERVICE

FULL SERVICE - LABOR FEES NOT INCLUDING PARTS


First Stage Labor - \$35

Octopus Labor - \$35

Second Stage Labor - \$35

Alternative Air Source Labor-\$35

Regulator Set-up (new) and Bench Test - \$95




With Pressure test Battery not included



COMPUTER BATTERY CHANGE- WATCH STYLE - \$75

With Pressure test Battery not included





Transmitter Battery Change - \$25Battery not included

RUSH SERVICE - \$25 3 business days

Cylinder Service

HYDROSTATIC TEST - EVERY 5 YEARS VISUAL INSPECTION - EVERY YEAR

VISUAL INSPECTION - \$15

VIP STICKER INCLUDED
O-RING AND FILL NOT INCLUDED

HYDRO TEST-\$44

O-RING, BURST DISC AND FILL NOT INCLUDED

VIP - EDDY Current TEST-\$30

VIP STICKER INCLUDED O-RING AND FILL NOT INCLUDED FOR ALUMINUM OLDER THAN 1990



Shown with Thermo Manifold

Valve Overhaul - \$25

VALVE KIT NOT INCLUDED

Doubles setup - \$20
Visual Inspection Of Doubles
with Eddy Test -\$80
Visual Inspection Of Doubles - \$50



O2 Clean Cylinder - \$30 O2 Clean Valve - \$30 Tumble Cylinder - \$30 Blasting Exterior of Cylinder - \$25